




ARROWHEAD
ROCKDRILL



R120 HYDRAULIC HAMMER PARTS MANUAL

R120 PARTS LIST

Diagram Number	Part Number	Description	Quantity
1	1131301	Moil Point	1
2	1131114	Lower Bush	1
3	1131102	Chuck Housing	1
4	1131311	Tool Retainer	2
5	1131115	Upper Bush	1
6	1131106	Lower Cylinder Liner	1
7	1131101	Main Body	1
8	1131104	Piston	1
9	1131105	Upper Cylinder Liner	1
10	1101107	Disc Spring Washer	2
11	1131108	Spacer	1
12	1131103	Cylinder Head	1
13	1121201	Valve Housing	1
14	1121202	Valve Bottom Plate	1
15	1121203	Valve Top Plate	1
16	1121204	Valve Spool	1
17	1121205	Plunger	1
18	1011395	Valve Plate Bolts	12
19	1011201	Pressure Plug	1
20	1131401	Seal Kit	1
21	1011105	Gas Valve Assembly	1
22	1011307	Hose Adaptors	1
23	1011307	Hose Adaptors	1
24	1011400	Valve to Body Bolts	12
25	1011120	Cylinder Head Bolt Assembly	8
26	1011115	Dowel Pins	4
27	1011102	Inspection Port Plug	1
28	1011401	Chuck Housing Bolt Assembly	4
29	1011104	Grease Nipple	1
30	1011395	Lower Liner Retaining Bolt	2
31	1011203	Lower Bush Bolt Assembly	8
32	1131302	Chisel	1
33	1131303	Blunt	1
34	1131314	Stopper Plate	2
35	1011395	Stopper Plate Bolt Assembly	8
36	1131309	Hammer Box	1
37	1131313	Decal Set	1
38	1131310	Lower Buffer	1
39	1131315	Upper Buffer	1
40	1121312	Top Bracket	1
41	1011373	Top Bracket Bolt Assembly	14
42	1011323	Pressure Hose (Europe)	1
43	1011330	Pressure Hose (Americas)	1
44	1011112	Gas Valve Spring	1
45	1011111	Gas Valve Shuttle	1
46	1011110	Gas Valve Small O Ring	1
47	1011108	Gas Valve Large O Ring	2
48	1011109	Gas Valve Dowty Washer	1
49	1011107	Gas Valve Body	1
50	1011106	Gas Valve Dust Cap	1



R120 POWERCELL BREAKDOWN




ARROWHEAD
ROCKDRILL



R120 HAMMER BREAKDOWN



ARROWHEAD
ROCKDRILL



GAS VALVE ASSEMBLY BREAKDOWN